ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
9

Ward Name
Vidyaranyapura

Street ID
W0317, W0154, W0485, W0315, W0332, W0553, W0551, W

Street Name
NA, R H B Colcny, 4th Crs, I T P L Main Rd, Doddenakundi Indstrial Rd

Significant Landmark
Thindlu Village

Segment No.
9/C-W0317/S042922

Total Length (m)
564.16

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	335.90	77.568462	13.073329	77.571519	13.072838	W0328	W0364
2	191.93	77.566912	13.073418	77.568581	13.073454	W0485	W0332
3	36.33	77.567532	13.074902	77.567568	13.075228	W0485	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of Concrete roads and Asphalt in Thindlu Village in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
2000000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Construction of Concrete roads and Asphalt in Thindlu Village in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
009-15-000009

Work Order No.
EE/BTP/BBMP/E-PMT/51/2014-15

Work Order Date
27/04/2015

Period of Extention
60 DAYS

Defect Liability Period From
27/04/2015

Defect Liability Period To
26/04/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B.CHANDRASHEKAR		0.00

Phone No.	E-Mail ID
9980496926	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		SURESH

Date of Inspection	Remarks
25/07/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0317, W0154, W0485, W0315,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/07/2016	24/08/2016	COMPLETED
SE	VASU K M	25/07/2016	24/08/2016	COMPLETED
EE	YARAPPA REDDY	25/07/2016	24/08/2016	COMPLETED
AEE	SHIVAKUMAR	25/07/2016	24/08/2016	COMPLETED
AE	SURESH	25/07/2016	24/08/2016	COMPLETED
AE	SURESH	25/07/2016	24/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0317, W0154, W0485, W0315,